

Function number	Test Station	Percent	Faults	Percent
PERFORM OPERATION	5	100.0	22	100.0
BASIC FUNCTIONS:	3	60.0	5	22.7
010000 FURNISH POWER	2	40.0	2	9.1
013000 CONVERT ENERGY	2	40.0	2	9.1
Responses:				
12 :2216:Engine races				
12 :2312:Engine races				
020000 PROPEL VEHICLE	2	40.0	2	9.1
022000 TRANSFER TORQUE	1	20.0	1	4.5
Responses:				
16 :2217:Moving to next gear it jumps into gear too fast				
023000 ENGAGE TRACTION	1	20.0	1	4.5
Responses:				
15 :2312:Would still roll when in park				
030000 CONTROL MOVEMENT	1	20.0	1	4.5
032000 CONTROL SPEED	1	20.0	1	4.5
Responses:				
18 :2213:Linkage loosened up				
SUPPORTING FUNCTIONS:	5	100.0	17	77.3
050000 ASSR CONVENIENCE	1	20.0	1	4.5
053000 AID SERVICE	1	20.0	1	4.5
053200 SIMPLIFY SERVICE	1	20.0	1	4.5
Responses:				
22 :2316:Hydraulic oil filter in canister/harder to change				
060000 ASSR DEPNDABILTY	5	100.0	12	54.5
061000 PREVENT DAMAGE	3	60.0	3	13.6
061300 RESIST BREAKAGE	3	60.0	3	13.6
Responses:				
31 :2124:Front knuckle in front drive shaft				
31 :2312:Repair on parking/transmission				
9 :2316:Seals in coupler for hydraulic system rip				
062000 MAINTAIN TASK	4	80.0	7	31.8
Responses:				
31 :2124:Front wheel assist gave some trouble				

Function number	Test Station	Percent	Faults	Percent
11 :2217:Linkage gets loose				
11 :2217:If set at 1500 RPM drops back/have to reset				
062100 ENSURE START	1	20.0	1	4.5
Responses:				
10 :2124:If it is very cold				
062300 REDUCE WEAR	3	50.0	3	13.6
Responses:				
17 :2217:Had to replace belts/help keep improper tension				
17 :2216:Replaced fan belt after 4000 hours				
3 :2316:Front tires wear out fast				
064000 PROTECT CROP	1	20.0	1	4.5
064200 ASSURE CLEARANCE	1	20.0	1	4.5
Responses:				
8 :2316: taller front tires/38" rather than 26"				
065000 PROTECT PERSONS	1	20.0	1	4.5
Responses:				
30 :2217:Use JICASE boosting lock/dangerous hooking cables to batt.				
070000 SATISFY USER	4	80.0	4	18.2
071000 INCREASE COMFORT	3	60.0	3	13.6
071400 ENTERTAIN OPERATOR	1	20.0	1	4.5
Responses:				
3 :2312:Put radio in different place/coo high				
071500 ASSURE SHOCK	2	40.0	2	9.1
Responses:				
29 :2216:Would like swivel seat & more room on side				
29 :2316:Doesn't pivot far enough				
072000 FACILITAT OPERATNS	1	20.0	1	4.5
072200 REDUCE EFFORT	1	20.0	1	4.5
Responses:				
8 :2217:Difficult shifting/should be smoother				