

Function number	Test Station	Percent	Faults	Percent
TASK: PERFRM OPERATION	1	100.0	317	100.0
BASIC FUNCTIONS:	1	100.0	106	33.4
010000 FURNISH POWER	1	100.0	1	0.3
012000 INGNITE MIXTURE	1	100.0	1	0.3
	2124		1	

## COMMENTS:

5: 4 :IT WAS COLD -- TURNED OVER SLOW -- USED ETHER AND IT STARTED

030000 CONTROL MOVEMENT	1	100.0	3	0.9
033000 CONTRL DIRECTION	1	100.0	3	0.9
	2124		3	

## COMMENTS:

39: 1 :IN TURNING CORNERS HAD TO TAKE FRONT WHEEL ASSIST OUT TO TURN EASIER

75: 1 :IN TURNING SHORT HAD TO TAKE IT OUT OF GEAR TO TURN

82: 1 :WITH FRONT WHEEL ASSIST IN GEAR -- IT DOESN'T TURN AS GOOD AS I WOULD LIKE IT TO

SUPPORTING FUNCTIONS:	1	100.0	211	66.6
060000 ASSR DEPNDABILTY	1	100.0	2	0.6
	2124		2	

## COMMENTS:

4: 1 :A LITTLE LOW -- ADDED SOME ENGINE OIL

89: 1 :GREASED THE TRACTOR AND LOADER

070000 SATISFY USER	1	100.0	3	0.9
071000 INCREASE COMFORT	1	100.0	1	0.3
071300 CNTRL ENVRNMENT	1	100.0	1	0.3
	2124		1	

## COMMENTS:

81: 4 :THE WINDOWS STEAMED UP AT FIRST UNTIL THE HEATER WARMED UP

072000 FACLITAT OPRATNS	1	100.0	3	0.9
072200 REDUCE EFFORT	1	100.0	3	0.9
	2124		3	

## COMMENTS:

25: 2 :P.T.O DISENGAGE FROM FEEDER WAGON CAN'T TURN TO TAKE OFF

<u>Function number</u>	<u>Test Station</u>	<u>Percent</u>	<u>Faults</u>	<u>Percent</u>
35: 2	:TAKING P.T.O STAFT OFF			