

Function number	Test Station	Percent	Faults	Percent
TASK: PERFORM OPERATION	1	100.0	373	100.0
BASIC FUNCTIONS:	1	100.0	118	31.6
010000 FURNISH POWER	1	100.0	1	0.3
012000 IGNITE MIXTURE	1	100.0	1	0.3
030000 CONTROL MOVEMENT	1	100.0	3	0.8
033000 CONTRL DIRECTION	1	100.0	3	0.8
SUPPORTING FUNCTIONS:	1	100.0	255	68.4
060000 ASSR DEPNDABILTY	1	100.0	2	0.5
070000 SATISFY USER	1	100.0	3	0.8
071000 INCREASE COMFORT	1	100.0	1	0.3
071300 CNTRL ENVRNMENT	1	100.0	1	0.3
072000 FACLITAT OPRATNS	1	100.0	7	1.9
072200 REDUCE EFFORT	1	100.0	7	1.9